Bill No. <u>CS for SB 1774</u>

Barcode 301660

```
CHAMBER ACTION
              Senate
                                                    House
             Comm: RCS
 1
       04/18/2006 03:22 PM
 2
 3
 4
 5
 б
 7
 8
 9
10
    The Committee on Regulated Industries (Posey) recommended the
11
12
    following amendment:
13
           Senate Amendment (with title amendment)
14
           On page 18, between lines 20 and 21,
15
16
17
    insert:
18
           Section 6. Present subsections (8) through (27) of
19
    section 633.021, Florida Statutes, are redesignated as
    subsections (9) through (28), respectively, and a new
20
21
    subsection (8) is added to that section, to read:
22
           633.021 Definitions.--As used in this chapter:
23
          (8) A "fire hydrant" is a connection to a water main,
    elevated water tank, or other source of water for the purpose
24
    of supplying water to a fire hose or other fire protection
25
   apparatus for fire-suppression operations.
26
           Section 7. Section 633.082, Florida Statutes, is
27
   amended to read:
28
           633.082 Inspection of fire control systems, fire
29
30
   hydrants, and fire protection systems .--
31
           (1) The State Fire Marshal shall have the right to
                                  1
    10:30 AM
               04/18/06
                                                  s1774c1c-ri24-t01
```

Florida Senate - 2006

COMMITTEE AMENDMENT

Bill No. <u>CS for SB 1774</u>

Barcode 301660

1	inspect any fire control system during and after construction
2	to determine that such system meets the standards set forth in
3	the laws and rules of the state.
4	(2) Fire <u>hydrants and fire</u> protection systems
5	installed in public and private properties, except one-family
6	or two-family dwellings, in this state shall be inspected
7	following procedures established in the nationally recognized
8	inspection, testing, and maintenance standards NFPA-24 and
9	standard NFPA-25 as set forth in the edition adopted by the
10	State Fire Marshal. Quarterly, annual, 3-year, and 5-year
11	inspections consistent with the contractual provisions with
12	the owner shall be conducted by the certificateholder or
13	permittees employed by the certificateholder pursuant to s.
14	633.521.
15	(3) The inspecting contractor shall provide to the
16	building owner <u>or hydrant owner</u> and the local authority having
17	jurisdiction a copy of the applicable inspection report
18	established under <u>this chapter</u> s. 633.071(3) . The maintenance
19	of fire <u>hydrant and fire</u> protection systems as well as
20	corrective actions on deficient systems is the responsibility
21	of the owner of the system or hydrant. This section does not
22	prohibit governmental entities from inspecting and enforcing
23	firesafety codes.
24	(4) At least once each year, each fire hydrant shall
25	be opened fully and the water allowed to flow until all
26	foreign materials have cleared the hydrant. The flow shall be
27	maintained for not less than 1 minute.
28	(5) If a fire hydrant is made nonfunctional by the
29	closing of a water supply valve, the valve must immediately be
30	tagged with a red tag that is boldly marked "nonfunctional"
31	and the local fire authority notified that the hydrant is
	10:30 AM 04/18/06 s1774clc-ri24-t01

```
Florida Senate - 2006
                                             COMMITTEE AMENDMENT
   Bill No. CS for SB 1774
                       Barcode 301660
1
   nonfunctional.
          Section 8. Section 633.5391, Florida Statutes, is
 2
 3
   repealed.
 4
5
   (Redesignate subsequent sections.)
 б
 7
   8
9
   And the title is amended as follows:
          On page 1, line 21, after the semicolon,
10
11
12
   insert:
13
          amending s. 633.021, F.S.; defining the term
          "fire hydrant" for the purpose of the Florida
14
15
          Fire Prevention Code; amending s. 633.082,
          F.S.; providing for the inspection of fire
16
          hydrants by the State Fire Marshal; requiring
17
          that each fire hydrant be opened fully at least
18
          once each year to clear foreign materials in
19
          the system; providing that a fire hydrant made
20
21
          nonfunctional by the closing of a water supply
22
          valve must immediately be tagged with a red tag
          that is boldly marked "nonfunctional";
23
          repealing s. 633.5391, F.S., relating to
24
25
          backflow prevention assembly inspection;
26
27
28
29
30
31
                                 3
                                               s1774c1c-ri24-t01
              04/18/06
   10:30 AM
```