

Bill No. SB 2054

Barcode 822042

CHAMBER ACTION

Senate

House

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31

Comm: RCS  
03/22/2007 04:08 PM

.  
. .  
. .  
. .  
. .  
. .

---

The Committee on Environmental Preservation and Conservation  
(Dockery) recommended the following amendment:

**Senate Amendment (with title amendment)**

On page 34, between lines 25 and 26,

insert:

Section 6. Present subsections (9) through (20) of  
section 403.861, Florida Statutes, are redesignated as  
subsections (10) through (21), respectively, and a new  
subsection (9) is added to that section, to read:

403.861 Department; powers and duties.--The department  
shall have the power and the duty to carry out the provisions  
and purposes of this act and, for this purpose, to:

(9) Require that an internal check-valve device that  
prevents intentional or accidental backflow contamination of  
the public water supply be installed in all new and  
replacement fire hydrants. Such device must not delay access  
to the water supply for fire protection.

(Redesignate subsequent sections.)

Bill No. SB 2054

Barcode 822042

1 ===== T I T L E    A M E N D M E N T =====

2 And the title is amended as follows:

3            On page 2, line 30, after the semicolon,

4

5 insert:

6            amending s. 403.861, F.S.; requiring fire

7            hydrants to have a device installed that

8            prevents the contamination of the water supply;

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31